

CatonXchange 1.1.5 Release Notes - V1.1.5.1

Associated with Software Version 1.1.5.339 (188 Byte ASI)
With FPGA 3.9 update

Compatible with all version of CatonXchange shipped



Introduction

This firmware and software update is a major new feature general release for CatonXchange.

Please read the instruction of update and user manual for detailed information about features and configuration.

This document is related with the program system and covers specific aspects of the firmware and software releases. This release notes do not reflect all changes between software versions. Minor changes and usage improvements in the web UI may not be shown.

About this release

Release Type	General Release to public and apply to all shipped version of CatonXchange
Release Name	CatonXchange 1.1.5.1
Release Files Name	CatonXchange-1.1.5.339-sw.patch and CatonXchange-3.9.1-fw.rbf
SW Version	1.1.5.339-20200620
FPGA Version	FPGA 3.9
Release Date	20th June 2021
Web UI	Recommended Google Chrome, Firefox, Safari, other browser might work but functionality cannot be guaranteed.

New Features

There is no new feature in this release.

Enhancement

ASI output - Enhanced stability for output.

RTMP/RTMPS—Pull - Enhanced stability for output..

UDP - enhanced stability for input and output.

Known Issues

TS Monitor - Current release version is very specific use and we are continue to improve and adjust parameters. TS_sync_loss and TS_byte_error only set off when ASI cable physically removed, but other items are display correctly when TS has been interrupted, such as Continues_count_error. To stop the TS Monitor for current stream, has to delete the stream by stopping it.

Network - LAN DNS has preset to follow WAN DNS.

Logs - logs are remain in the device after factory reset.

CatonLink - settings remain in the device after factory reset.

RTMP Push - support up to 7mbps pushing to CDNs.

All the above known issue has been schedule for next firmware and software enhancement.

Update consideration

- Caton recommends a factory reset under the Advanced menu prior to updating firmware.
- Before proceed to firmware or software update, CatonXchange will required reboot and stopping all the active stream. Do not attempt any firmware or software update while transmission is in progress, be sure CatonXchange is in the stopped mode before performing an update.
- When the firmware or software being update, it will take about few minutes, the web browser will lose its connection. A refresh of the web browser will reconnect the web UI.
- There is no order when updating firmware and software, just make sure update both one by one.
- Do not interrupt the power while being update on both firmware and software.

Technical support

Caton technical support will answer and resolve issues for your CatonXchange.

Email: support@catontechnology.com